

Annexure D

BUILDING SAFETY CERTIFICATE

No.

575

Dated: 28/8/25

It is certified that the existing building Pragya, S.R. Sec. School..... (name of the building or premises) at V.S. Bhandwa, P.O. Badha, Teh. Badha, Distt. Ch. Dadri..... Haryana..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1) MAIN	Block (2) TOILET	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 1st floor	Single floor				

The building is owned/occupied by..... Pragya Shiksha Samiti..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D., B.R. Ch. Dadri. (Name of Department/ Govt.) on 28-8-2025.....(date of inspection) in the presence of Yashwant Singh (Secretary) Bhandwa, Ch. Dadri.....(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 28/8/25.... for a period of 01..... years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 28/8/25..... at Ch. Dadri..... by SDE (P) Ch. Dadri

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :

Name : Dilbag Singh

Designation : SAC

Name & Address of Department/ Office: PWD B.R

Branch Charkhi Dadri

Sub Divisional Engineer
Provl. Sub Division
P.W.D. B&R, Ch. Dadri